

BORE-MAX SPEED BRUSH - REAL AVID 9MM/380 CALIBER BORE-MAX SPEED BRUSH

[Gun Cleaning & Chemicals](#) > [Brushes & Bore Snakes](#) > [Bore Brushes](#)

The Bore-Max Speed Brush is a component of the Bore-Max Speed Clean System for faster and easier bore cleaning. Carbon build-up not only affects performance and accuracy, but also causes degradation of the bore. Carbon build-up also insulates the copper fouling in the bore making it difficult to dissolve and remove with bore solvent. Using a bore brush to remove this carbon build-up is the best way to tackle the job. In order to achieve maximize effectiveness, there needs to be an optimal balance between bristle density and bristle flexibility. Having too few bristles is a waste of time and too many won't provide enough flexibility to navigate the lands and grooves of the bore. The bristle configuration of the Bore-Max Speed Brush provides maximum scrubbing density removing more carbon with each pass and getting maximum results faster.



Attributes

- Name: [REAL AVID 9MM/380 CALIBER BORE-MAX SPEED BRUSH](#)
- Manufacturer: [REAL AVID](#)
- Product no.: 100047678
- Mfr. No.: AVBMSB9MM
- Caliber: 375 Caliber (.375), 9 mm (.355-.356)
- Style: Handgun
- Delivery weight: 0.045kg
- Shipping height: 13mm
- Shipping width: 70mm
- Shipping length: 171mm
- UPC: 813119013454

Table of Contents

- Startpage
- BOREMAX SPEED BRUSH SAFETY INSTRUCTIONS
- About Us

BOREMAX SPEED BRUSH SAFETY INSTRUCTIONS

Introduction

Thank you for choosing the BOREMAX SPEED BRUSH. This guide provides essential safety instructions and usage guidelines to ensure safe and effective use of the product. Please read this document carefully before using the BoreMax Speed Brush.

General Safety Guidelines

- Ensure that the BoreMax Speed Brush is used according to the manufacturer's instructions.
- Keep the product out of reach of children and vulnerable individuals.
- Regularly inspect the brush for any signs of wear or damage before use.
- Do not use the brush for any purpose other than its intended use.
- Report any unsafe conditions or accidents to the appropriate authorities.

Specific Safety Precautions for Use

- Always wear safety glasses to protect your eyes from debris when cleaning the bore.
- Handle the brush with care to avoid injury from sharp bristles.
- Avoid using excessive force when cleaning to prevent damage to the bore or the brush.
- Store the brush in a dry place to prevent corrosion or deterioration.
- Do not use the brush if it is damaged or if bristles are missing.

Instructions for Installation and Usage

1. Preparation:

- Ensure the firearm is unloaded and pointed in a safe direction.
- Gather all necessary cleaning supplies, including the BoreMax Speed Brush and bore solvent.

2. Using the BoreMax Speed Brush:

- Insert the BoreMax Speed Brush into the bore of the firearm.
- Apply a suitable bore solvent to the brush for enhanced cleaning.
- Move the brush back and forth through the bore with a gentle, steady motion.
- Repeat the process as necessary until the bore is clean.

3. PostCleaning Care:

- After cleaning, remove the brush from the bore and clean it according to the manufacturer's instructions.
- Store the brush in a protective case or holder when not in use.

Disposal Instructions

- Dispose of the BoreMax Speed Brush in accordance with local waste disposal regulations.
- If the brush is damaged or worn out, consider recycling the materials if possible.

Contact Information for Further Support

For any questions or concerns regarding the BOREMAX SPEED BRUSH, please refer to the manufacturer's contact information provided with the product packaging.

Thank you for your attention to these safety instructions. Enjoy the benefits of a cleaner bore and improved firearm performance with the BOREMAX SPEED BRUSH.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk