


SINCLAIR LOAD LABELS - LOAD LABELS 50 PACK

[Shooting Accessories](#) > [Ammunition Storage](#) > [Ammo Box Accessories](#)

Our Load Labels are printed on special label material called Pressables that can be applied, moved, and reapplied to almost any surface. We included space for load data, # of times fired, # of times trimmed, etc.



Attributes

- Name: [LOAD LABELS 50 PACK](#)
- Manufacturer: [SINCLAIR INTERNATIONAL](#)
- Product no.: 749000447
- Mfr. No.:
- Style: Label
- Quantity: 50
- Delivery weight: 0.023kg
- Shipping height: 10mm
- Shipping width: 97mm
- Shipping length: 155mm

Item details

Made in USA

Table of Contents

- Startpage
- SINCLAIR LOAD LABELS 50 PACK Safety Instruction Guide
- About Us

SINCLAIR LOAD LABELS 50 PACK Safety Instruction Guide

Introduction

Thank you for choosing the SINCLAIR LOAD LABELS 50 PACK. These load labels are designed to assist you in organizing and tracking your ammunition loads effectively. This guide provides essential safety instructions and guidelines to ensure the safe use of this product in compliance with the EU General Product Safety Regulation (GPSR).

General Safety Guidelines

- Ensure that the labels are used only for their intended purpose.
- Avoid using the labels on surfaces that may be damaged by adhesive materials.
- Keep the labels out of reach of children and vulnerable individuals.
- Regularly check the labels for wear and tear to ensure they remain safe and effective.

Specific Safety Precautions for Use

- Always apply the labels to clean and dry surfaces for optimal adhesion.
- If you need to reposition a label, do so gently to avoid tearing or damaging it.
- Do not expose the labels to extreme temperatures or direct sunlight for prolonged periods.
- If the label becomes damaged, discontinue use and dispose of it properly.

Instructions for Installation and Usage

1. Preparing the Surface

- Clean the surface where the label will be applied to ensure it is free of dust, dirt, and moisture.

2. Applying the Label

- Carefully peel the label from its backing.
- Align the label with the desired position on the surface.
- Press down firmly in the center and work your way outwards to eliminate air bubbles.

3. Repositioning the Label

- If you need to move the label, gently lift it from one corner and slowly peel it away from the surface.
- Reapply the label following the same steps as above.

4. Tracking Load Data

- Use a permanent marker or pen to fill in the designated spaces for load data, number of times fired, and number of times trimmed.

5. Removing the Label

- To remove the label, gently peel it off from one corner. If adhesive residue remains, use a suitable adhesive remover.

Disposal Instructions

- Dispose of any used or damaged labels in accordance with local waste disposal regulations.
- Do not incinerate the labels as they may release harmful substances.

Contact Information for Further Support

For safety inquiries or further assistance regarding the SINCLAIR LOAD LABELS 50 PACK, please refer to the official website or customer service channels.

By following these guidelines, you can ensure the safe and effective use of your SINCLAIR LOAD LABELS. Thank you for your attention to safety!

About Us

Brownells Austria

Brownells - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

www.brownells.at