

LOCK-N-LOAD AP POWDER FUNNEL DIE

[Reloading](#) > [Powder Handling](#) > [Powder Funnels](#)

For ultra precision on the Lock-N-Load AP™ press, this die allows handloaders to trickle and weigh each individual powder charge and drop the charge into the cartridge case.



Attributes

- Name: [LOCK-N-LOAD AP POWDER FUNNEL DIE](#)
- Manufacturer: [HORNADY](#)
- Product no.: 749016787
- Mfr. No.: 095360
- Delivery weight: 0.272kg
- Shipping height: 76mm
- Shipping width: 102mm
- Shipping length: 102mm
- UPC: 090255953602

Table of Contents

- Startpage
- LOCKNLOAD AP POWDER FUNNEL DIE Safety Instruction Guide
- About Us

LOCKNLOAD AP POWDER FUNNEL DIE Safety Instruction Guide

Introduction

Thank you for choosing the LOCKNLOAD AP POWDER FUNNEL DIE by HORNADY. This product is designed for handloaders who require precision in measuring and dispensing powder charges. To ensure safe and effective use of this product, please read this safety instruction guide carefully before use.

General Safety Guidelines

- Always handle the LOCKNLOAD AP POWDER FUNNEL DIE with care to avoid accidents.
- Keep the product out of reach of children and vulnerable individuals.
- Use the product only for its intended purpose, which is to dispense powder into cartridge cases.
- Regularly inspect the die for any signs of wear or damage before each use.
- If you encounter any issues with the product, cease use immediately and seek assistance.

Specific Safety Precautions for Use

- Ensure that you are working in a wellventilated area to avoid inhaling any powder particles.
- Avoid using excessive force when trickling powder to prevent spills and mishaps.
- Always wear appropriate personal protective equipment (PPE), such as safety glasses and gloves, when handling powders.
- Do not eat, drink, or smoke while handling powder to prevent contamination and health risks.
- Keep your workspace clean and organized to minimize the risk of accidents.

Instructions for Installation and Usage

Installation

1. **Prepare Your Workspace:** Ensure your work area is clean and free of distractions.
2. **Attach the Funnel Die:**
 - Place the funnel die onto the LockNLoad AP press.
 - Secure it tightly to prevent any movement during operation.
3. **Check Alignment:** Ensure that the funnel die is properly aligned with the cartridge case to avoid misfeeds.

Usage

1. **Set Up Your Scale:** Before using the funnel die, ensure your scale is calibrated and ready for use.
2. **Trickle Powder:**
 - Carefully pour the desired amount of powder into the funnel die.
 - Use the trickler to dispense powder slowly into the cartridge case.
3. **Weigh Charges:** After dispensing, weigh each charge to ensure accuracy.
4. **Drop Charges:** Once weighed, drop each charge into the appropriate cartridge case.

Disposal Instructions

- Dispose of any unused powder according to local regulations.
- Do not dispose of powder in regular waste. Contact local authorities for proper disposal methods.
- Recycle packaging materials where possible.

Contact Information for Further Support

For any inquiries or safety concerns regarding the LOCKNLOAD AP POWDER FUNNEL DIE, please refer to the manufacturer's contact information provided with the product packaging.

Conclusion

By following these safety instructions, you can ensure a safe and effective experience while using the LOCKNLOAD AP POWDER FUNNEL DIE. Always prioritize safety and compliance with local regulations when handling and using this product. Thank you for your attention to these guidelines.

About Us

Brownells Česká republika

Brownells - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

www.brownells.cz