

# X-SKEL MOUNTS - WARNE MFG. COMPANY 1" ULTRA HIGH (1.435") 0 MOA MOUNT, RED

[Optics & Mounting](#) > [Rings, Mounts & Bases](#) > [Mount Sets](#)

Warne Scope Mounts is excited to introduce their second generation SKEL mount, the X-SKEL. This new MSR mount offers an additional 1" of forward cantilever, and 1 piece clamp design for added strength. The rugged, lightweight design of the X-SKEL maintains our famous Return to Zero capability, and utilizes 1/2" hex nuts for rock solid attachment. It features a skeletonized ring body and caps for reduced weight and steel threaded cap inserts for maximum durability. The X-SKEL places your optic at the IDEAL HEIGHT with a generous cantilever for proper eye relief, it will easily accommodate the longer eyepieces found on many of today's scopes. Lightweight, skeletonized aluminum body and caps to reduce overall weight without sacrificing reliability. #8 Torx style fasteners with steel threaded inserts to prevent stripping. Additional 1 Inch cantilever forward design to provide additional eye relief. Places your optic at the Ideal Height for MSR and similar platforms. 1/2" tactical nut attachment, 65 in/lb. of torque is recommended.



## Attributes

- Name: [WARNE MFG. COMPANY 1" ULTRA HIGH \(1.435"\) 0 MOA MOUNT, RED](#)
- Manufacturer: [WARNE MFG. COMPANY](#)
- Product no.: 947000378
- Mfr. No.: XSKE1R
- Elevation: -
- Finish: Red
- Height: -
- Scope Tube Diameter: 1"
- Style: Competition,3-Gun
- Delivery weight: 0.254kg
- UPC: 656813104826

## Item details

Made in USA

# Table of Contents

- Startpage
- XSKELETON MOUNTS WARNE MFG. COMPANY 1" ULTRA HIGH (1.435") 0 MOA MOUNT, RED
- About Us

# XSKELE MOUNTS WARNE MFG. COMPANY 1" ULTRA HIGH (1.435") 0 MOA MOUNT, RED

## Consumer Safety Instruction Guide

### Introduction

Thank you for choosing the XSKELE MOUNTS WARNE MFG. COMPANY 1" ULTRA HIGH (1.435") 0 MOA MOUNT, RED. This guide provides essential safety instructions, usage guidelines, and disposal instructions to ensure the safe and effective use of your product. Please read this manual thoroughly before installation and use to familiarize yourself with safety precautions and proper handling.

### General Safety Guidelines

To ensure the safe use of the XSKELE mount, please adhere to the following guidelines: \* Always inspect the mount for any visible damage before use. \* Ensure that the mount is compatible with your scope and firearm before installation. \* Use the mount only for its intended purpose. \* Keep the mount out of reach of children and vulnerable individuals. \* Follow all local laws and regulations regarding firearm accessories. \* Store the mount in a cool, dry place when not in use. \* Regularly check for wear and tear, especially on fasteners and attachment points.

### Specific Safety Precautions for Use

When using the XSKELE mount, please observe the following precautions: \* Ensure that the mount is securely attached to your firearm before use. \* Use a torque wrench to tighten the 1/2" tactical nut attachment to a recommended torque of 65 in/lb. \* Do not exceed the manufacturer's specifications for scope weight and dimensions. \* Avoid using the mount in extreme weather conditions without proper preparation. \* If you notice any unusual sounds or instability during use, discontinue use immediately and inspect the mount. \* Be cautious when handling the mount, as sharp edges may be present.

### Instructions for Installation and Usage

To ensure proper installation and usage of the XSKELE mount, follow these steps: 1. **Preparation** \* Gather all necessary tools, including a torque wrench and appropriate screwdrivers. \* Ensure the firearm is unloaded and pointed in a safe direction.

#### 1. Installation

- Align the mount with the scope tube and the firearm's rail.
- Insert the steel threaded inserts into the mount's clamp.
- Secure the mount using the #8 Torx style fasteners, ensuring they are tightened evenly.
- Use a torque wrench to tighten the tactical nut attachment to 65 in/lb.
- Check for stability and alignment before proceeding.

#### 2. Usage

- Once installed, adjust your optic for proper eye relief.
- Test the mount by gently shaking the firearm to ensure it is secure.
- Maintain a safe shooting environment and follow all firearm safety protocols.

### Disposal Instructions

When disposing of the XSKELE mount, please consider the following: \* Follow local regulations for the disposal of metal and plastic materials. \* If the mount is damaged or no longer usable, recycle it where possible. \* Do not

dispose of the mount in household waste.

## **Contact Information for Further Support**

For further assistance or inquiries regarding the XSkel mount, please refer to the manufacturer's contact information available on the product packaging or website.

## **Conclusion**

By following these safety instructions and guidelines, you can ensure a safe and effective experience with the XSkel Mounts Warne Mfg. Company 1" Ultra High (1.435") 0 MOA Mount, Red. Your safety and satisfaction are our top priorities. Thank you for your attention to these important safety measures.

# About Us

## **Brownells Europe**

### **Brownells Europe - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories**

P.O.Box 4300   
Warwick   
CV34 9BR

[www.brownells.eu](http://www.brownells.eu)