

# X-SKEL MOUNTS - WARNE MFG. COMPANY 34MM ULTRA HIGH (1.435") 0 MOA MOUNT, BLACK

[Optics & Mounting](#) > [Rings, Mounts & Bases](#) > [Mount Sets](#)

Warne Scope Mounts is excited to introduce their second generation SKEL mount, the X-SKEL. This new MSR mount offers an additional 1" of forward cantilever, and 1 piece clamp design for added strength. The rugged, lightweight design of the X-SKEL maintains our famous Return to Zero capability, and utilizes  $\frac{1}{2}$ " hex nuts for rock solid attachment. It features a skeletonized ring body and caps for reduced weight and steel threaded cap inserts for maximum durability. The X-SKEL places your optic at the IDEAL HEIGHT with a generous cantilever for proper eye relief, it will easily accommodate the longer eyepieces found on many of today's scopes. Lightweight, skeletonized aluminum body and caps to reduce overall weight without sacrificing reliability. #8 Torx style fasteners with steel threaded inserts to prevent stripping. Additional 1 Inch cantilever forward design to provide additional eye relief. Places your optic at the Ideal Height for MSR and similar platforms. 1/2" tactical nut attachment, 65 in/lb. of torque is recommended.



## Attributes

- Name: [WARNE MFG. COMPANY 34MM ULTRA HIGH \(1.435"\) 0 MOA MOUNT, BLACK](#)
- Manufacturer: [WARNE MFG. COMPANY](#)
- Product no.: 947000389
- Mfr. No.: XSKEL34TW
- Elevation: 0 MOA
- Finish: Black
- Height: 1.435"
- Scope Tube Diameter: 34mm
- Style: 3-Gun, Competition
- Delivery weight: 0.259kg
- Shipping height: 25mm
- Shipping width: 165mm
- Shipping length: 184mm
- UPC: 656813104963

## Item details

Made in USA

# Table of Contents

- Startpage
- XSKELE Mounts Safety Instruction Guide
- About Us

# XSKELE Mounts Safety Instruction Guide

## Introduction

Thank you for choosing the XSKELE Mounts by Warne MFG. Company. This guide provides important safety instructions and guidelines to ensure the safe use of your product. Please read this guide carefully before installation and use.

## General Safety Guidelines

- Ensure that the product is used in accordance with the manufacturer's instructions.
- Always check the mount for any signs of damage before each use.
- Do not exceed the recommended torque specifications during installation.
- Keep the mount and all components out of reach of children.
- Report any unsafe products or accidents to the appropriate authorities.
- Stay updated on recall notices and safety alerts through the EU's Safety Gate platform.

## Specific Safety Precautions for Use

### • Potential Hazards:

- Improper installation may lead to optic misalignment or detachment.
- Excessive torque can damage the mount or the firearm.
- Failure to secure the mount properly may result in loss of the optic during use.

### • Instructions to Avoid Hazards:

- Follow the installation instructions carefully.
- Use a torque wrench to ensure that the recommended torque of 65 in/lb. is not exceeded.
- Regularly inspect the mount for any loose components before each use.

### • Warnings:

- This product is not intended for use by children.
- Always ensure that the firearm is unloaded before installation or adjustment of the mount.

## Instructions for Installation and Usage

### 1. Preparation:

- Ensure the firearm is unloaded and pointed in a safe direction.
- Gather all necessary tools, including a torque wrench and #8 Torx style fasteners.

### 2. Installation Steps:

- Align the XSKELE mount with the appropriate mounting points on your firearm.
- Using the #8 Torx fasteners, secure the mount to the firearm.
- Tighten the fasteners gradually in a crisscross pattern to ensure even pressure.
- Use a torque wrench to tighten the fasteners to a maximum of 65 in/lb.

### 3. Usage:

- Once installed, place your optic into the mount.
- Adjust the optic to the desired position for proper eye relief.

- Ensure that the optic is securely fastened before use.

#### **4. PostInstallation Check:**

- After installation, perform a function check to ensure that the mount and optic are secure.
- Inspect the mount periodically for any signs of wear or damage.

## **Disposal Instructions**

- Dispose of the product in accordance with local regulations for electronic and metal waste.
- Do not dispose of the product in regular household waste.
- Consider recycling options for materials when possible.

## **Contact Information for Further Support**

For any inquiries or further assistance regarding the XSKEL Mounts, please refer to the contact information provided on the packaging or visit the official Warne MFG. Company website.

By following these safety instructions, you can ensure the safe and effective use of your XSKEL Mounts. Thank you for your commitment to safety.

# About Us

## Brownells UK

### **Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories**

Unit 1, Laughing Dog Industrial Estate  
London Road  
Rugby  
Warwickshire  
CV23 9LP

[www.brownells.co.uk](http://www.brownells.co.uk)