

Bore Mop, 3 pk - Bore Mop 10/12 Gauge , 3 pk

[Gun Cleaning & Chemicals](#) > [Patches & Mops](#) > [Bore Mops](#)

100% Cotton Mops are ultra-absorbent. They hold and carry solvents, lubes and preservatives into your bore and chamber. Great for applying large quantities of modern copper solvents to fouled bores.

NO IMAGE
AVAILABLE

Attributes

- Name: [Bore Mop 10/12 Gauge , 3 pk](#)
- Manufacturer: [TIPTON](#)
- Product no.: EU1001122
- Mfr. No.: 657972
- Caliber: 12 Gauge
- Delivery weight: 0.04kg
- Shipping height: 73mm
- Shipping width: 52mm
- Shipping length: 178mm
- UPC: 661120579724

Table of Contents

- Startpage
- Tipton Bore Mop Safety Instructions
- About Us

Tipton Bore Mop Safety Instructions

Introduction

Thank you for choosing the Tipton Bore Mop, designed for effective cleaning of 10/12 gauge firearms. This safety instruction guide provides essential information to ensure safe and proper use of the product. Please read this guide carefully before using the Bore Mop.

General Safety Guidelines

- Always use the Bore Mop in a wellventilated area to avoid inhaling fumes from solvents and lubricants.
- Keep the Bore Mop and all cleaning materials out of reach of children and pets.
- Use personal protective equipment (PPE) such as gloves and safety glasses when handling solvents and lubricants.
- Avoid using the Bore Mop near open flames or heat sources, as solvents may be flammable.
- Do not use the Bore Mop for any purpose other than cleaning firearms.

Specific Safety Precautions for Use

- Ensure the firearm is unloaded before using the Bore Mop.
- Do not insert the Bore Mop into the barrel of a firearm unless you are certain it is safe to do so.
- Use only recommended solvents and lubricants that are compatible with your firearm.
- Inspect the Bore Mop for any signs of damage or wear before each use. Do not use if damaged.
- Dispose of used Bore Mops and cleaning materials in accordance with local regulations.

Instructions for Installation and Usage

1. Preparation

- Ensure the firearm is completely unloaded and pointed in a safe direction.
- Gather all necessary cleaning materials, including the Bore Mop, solvents, and lubricants.

2. Using the Bore Mop

- Attach the Bore Mop to a cleaning rod or handle as per the manufacturer's instructions.
- Apply a suitable solvent or lubricant to the Bore Mop, ensuring it is adequately soaked but not dripping.
- Insert the Bore Mop gently into the bore of the firearm, ensuring it is properly aligned.
- Pull the Bore Mop through the bore in one smooth motion. Do not force it.
- Repeat the process as necessary, using additional solvent or lubricant as needed.

3. PostCleaning Care

- After cleaning, inspect the Bore Mop for any residue or damage.
- Clean the Bore Mop according to the manufacturer's instructions, if applicable.
- Store the Bore Mop in a cool, dry place away from direct sunlight.

Disposal Instructions

- Dispose of used Bore Mops and any cleaning materials in accordance with local waste management regulations.
- Do not dispose of solvents or lubricants in the household waste. Follow local guidelines for hazardous waste disposal.

Contact Information for Further Support

For any inquiries or further assistance regarding the Tipton Bore Mop, please refer to the product packaging or visit the manufacturer's website.

By following these safety instructions, you can ensure safe and effective use of the Tipton Bore Mop. Always prioritize safety in all cleaning activities. Thank you for your attention to these guidelines.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk