

INGOT MOULD - REDDING SAECO INGOT MOULD

[Reloading](#) > [Bullet Casting](#) > [Casting Moulds](#) > [Ingot Moulds](#)

INGOT MOULD



Attributes

- Name: [REDDING SAECO INGOT MOULD](#)
- Manufacturer: [REDDING](#)
- Product no.: 100020359
- Mfr. No.: 23000
- Delivery weight: 0.971kg
- Shipping height: 25mm
- Shipping width: 102mm
- Shipping length: 165mm
- UPC: 611760230004

Item details

Made in USA

Table of Contents

- [Startpage](#)
- [INGOT MOULD REDDING SAECO INGOT MOULD Safety Instructions](#)
- [About Us](#)

INGOT MOULD REDDING SAECO INgot MOULD

Safety Instructions

Introduction

Thank you for choosing the INGOT MOULD REDDING SAECO INgot MOULD. This safety instruction guide is designed to help you use this product safely and effectively. Please read this document thoroughly before using the ingot mould to ensure a safe and enjoyable experience.

General Safety Guidelines

- Ensure that the ingot mould is used only for its intended purpose.
- Always inspect the ingot mould for any signs of damage or wear before use.
- Keep the ingot mould out of reach of children and vulnerable individuals.
- Use personal protective equipment (PPE) such as gloves and safety goggles when handling hot materials.
- Follow all local regulations and guidelines regarding the use of metal casting equipment.

Specific Safety Precautions for Use

- Always work in a wellventilated area to avoid inhaling fumes.
- Never exceed the maximum temperature rating of the ingot mould.
- Avoid pouring molten metal directly onto the mould; instead, use a ladle to prevent splashing.
- Do not leave the ingot mould unattended while in use.
- Allow the mould to cool completely before handling or cleaning.
- Be cautious of sharp edges and hot surfaces during and after use.

Instructions for Installation and Usage

1. Preparation:

- Ensure your workspace is clean and free of clutter.
- Gather all necessary tools and materials before starting.

2. Setting Up the Mould:

- Place the ingot mould on a stable, heatresistant surface.
- Make sure the mould is secure and will not tip over during use.

3. Melting Metal:

- Use a suitable furnace or heat source to melt the metal.
- Monitor the temperature carefully to avoid overheating.

4. Pouring:

- Once the metal is molten, use a ladle to carefully pour it into the ingot mould.
- Avoid pouring directly from the furnace to prevent accidents.

5. Cooling:

- Allow the metal to cool and solidify in the mould.
- Do not attempt to remove the ingot until it is completely cooled.

6. Cleaning:

- After use, clean the ingot mould with appropriate cleaning agents.
- Store the mould in a dry place to prevent rust and damage.

Disposal Instructions

- Dispose of any waste materials in accordance with local regulations.
- Do not throw the ingot mould in regular trash if it is damaged; check with local waste management for proper disposal methods.

Contact Information for Further Support

For any safety inquiries or concerns regarding the INGOT MOULD REDDING SAECO INGOT MOULD, please reach out to the designated EU contact point provided with your product documentation.

Important Note: Always stay informed about product recalls and safety alerts. You can check for updates on the EU's Safety Gate platform to ensure your safety and that of others. Report any unsafe products or accidents to the appropriate authorities.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk