

# BORE-MAX SPEED BRUSH - REAL AVID 22/223 CALIBER BORE-MAX SPEED BRUSH

[Gun Cleaning & Chemicals](#) > [Brushes & Bore Snakes](#) > [Bore Brushes](#)

The Bore-Max Speed Brush is a component of the Bore-Max Speed Clean System for faster and easier bore cleaning. Carbon build-up not only affects performance and accuracy, but also causes degradation of the bore. Carbon build-up also insulates the copper fouling in the bore making it difficult to dissolve and remove with bore solvent. Using a bore brush to remove this carbon build-up is the best way to tackle the job. In order to achieve maximize effectiveness, there needs to be an optimal balance between bristle density and bristle flexibility. Having too few bristles is a waste of time and too many won't provide enough flexibility to navigate the lands and grooves of the bore. The bristle configuration of the Bore-Max Speed Brush provides maximum scrubbing density removing more carbon with each pass and getting maximum results faster.



## Attributes

- Name: [REAL AVID 22/223 CALIBER BORE-MAX SPEED BRUSH](#)
- Manufacturer: [REAL AVID](#)
- Product no.: 100047668
- Mfr. No.: AVBMSB223
- Caliber: 22 Caliber (.223-.224)
- Style: Rifle
- Delivery weight: 0.045kg
- Shipping height: 13mm
- Shipping width: 70mm
- Shipping length: 171mm
- UPC: 813119013362

# Table of Contents

- Startpage
- BoreMax Speed Brush Safety Instruction Guide
- About Us

# BoreMax Speed Brush Safety Instruction Guide

## Introduction

Thank you for choosing the BoreMax Speed Brush, a key component of the BoreMax Speed Clean System designed to enhance your bore cleaning experience. This guide provides essential safety instructions to ensure the safe and effective use of the product in compliance with the EU General Product Safety Regulation (GPSR).

## General Safety Guidelines

- Ensure that the BoreMax Speed Brush is used only for its intended purpose.
- Always inspect the brush for any damage before use. Do not use if damaged.
- Keep the product out of reach of children and vulnerable individuals.
- Use the brush in a wellventilated area to avoid inhaling any dust or debris.
- Follow all local regulations regarding the disposal of cleaning materials and components.

## Specific Safety Precautions for Use

- Wear appropriate protective eyewear when using the BoreMax Speed Brush to protect against flying debris.
- Use gloves to prevent skin irritation from cleaning solvents or chemicals.
- Avoid using excessive force while cleaning to prevent damage to the bore or the brush.
- Do not use the BoreMax Speed Brush with solvents that are not compatible with the materials of the brush.
- Ensure that the firearm is unloaded and pointed in a safe direction before using the brush.

## Instructions for Installation and Usage

### 1. Preparation:

- Ensure the firearm is unloaded and in a safe position.
- Gather necessary cleaning materials, including bore solvent and a cleaning rod.

### 2. Installation:

- Attach the BoreMax Speed Brush to your cleaning rod securely.
- Ensure the brush is properly aligned and locked in place to prevent detachment during use.

### 3. Usage:

- Apply an appropriate bore solvent to the brush to enhance cleaning effectiveness.
- Insert the brush into the bore and gently scrub back and forth to remove carbon buildup.
- Use a moderate amount of pressure; excessive force may damage the bore or brush.
- After cleaning, remove the brush from the bore and wipe away any excess solvent.

### 4. PostUsage:

- Clean the BoreMax Speed Brush with warm water and mild soap to remove any residue.
- Store the brush in a dry place away from direct sunlight and moisture.

## Disposal Instructions

- Dispose of used cleaning solvents and materials in accordance with local regulations.
- The BoreMax Speed Brush can be disposed of with regular household waste, provided it is not

contaminated with hazardous materials.

- For further disposal instructions, consult local waste management authorities.

## Contact Information for Further Support

For any safety inquiries or concerns regarding the BoreMax Speed Brush, please reach out to the designated EU contact point associated with this product.

By following these safety instructions, you can ensure a safe and effective cleaning experience with your BoreMax Speed Brush. Always prioritize safety and compliance with local regulations when using cleaning products.

# About Us

## Brownells UK

### **Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories**

Unit 1, Laughing Dog Industrial Estate  
London Road  
Rugby  
Warwickshire  
CV23 9LP

[www.brownells.co.uk](http://www.brownells.co.uk)