

BORE-MAX SPEED JAG & PATCH COMBO - REAL AVID 9MM/380 CALIBER BORE-MAX JAG & BORE-MAX SPEED PATCHES 25CT

[Gun Cleaning & Chemicals](#) > [Cleaning Rods & Accessories](#) > [Cleaning Rod Jags](#)

Bore-Max Speed Jag and Patches are components of the Bore-Max Speed Clean System for faster and easier bore cleaning. Within the bore, carbon and copper fouling build-up in layers over time and cumulatively have a significant impact on a firearms performance if left unchecked. The carbon build-up essentially insulates the copper fouling from the outside in. Carbon layers need to be removed mechanically with a bore brush in order to fully expose the copper layers beneath. Alternately, copper must be chemically dissolved in order to remove it from the bore, as a brush is ineffective at breaking loose these heat-melded deposits. Sized to account precisely for both the jag diameter and patch thickness this Speed Jag and Patch combo provides the optimal compression to thoroughly and consistently reach into the lands and grooves. Tight enough to provide superior compression within the bore while still remaining relatively easy to push through. The Speed Jag and Patch system gets more patch material in the bore, eliminates bunching and maximizes the effectiveness of each pass-through. Speed Patches are a synthetic material that has shown to have superior absorbency over cotton. This material is better at absorbing fouling and spent solvent in the bore and is more effective at picking up and trapping crud.



Attributes

- Name: [REAL AVID 9MM/380 CALIBER BORE-MAX JAG & BORE-MAX SPEED PATCHES 25CT](#)
- Manufacturer: [REAL AVID](#)
- Product no.: 100047690
- Mfr. No.: AVBMJAG9MM
- Caliber: 357 Caliber, 380 Caliber, 9mm
- Delivery weight: 0.045kg
- Shipping height: 13mm
- Shipping width: 70mm
- Shipping length: 171mm
- UPC: 813119013560

Table of Contents

- [Startpage](#)
- [Safety Instruction Guide for BOREMAX SPEED JAG & PATCH COMBO](#)
- [About Us](#)

Safety Instruction Guide for BOREMAX SPEED JAG & PATCH COMBO

Introduction

Thank you for choosing the BOREMAX SPEED JAG & PATCH COMBO. This product is designed to enhance your bore cleaning experience for firearms in the 9mm and .380 caliber range. It is important to follow safety guidelines to ensure safe and effective use. This guide outlines essential safety instructions, precautions, and proper usage to help you maintain your firearm safely.

General Safety Guidelines

- Ensure the product is used only for its intended purpose.
- Keep this product out of reach of children and vulnerable individuals.
- Regularly check for any signs of wear or damage to the product before use.
- Always follow the manufacturer's instructions for use and care.
- Report any unsafe product conditions or accidents to the appropriate authorities.
- Stay informed about product recalls via the EU Safety Gate platform.

Specific Safety Precautions for Use

- Always handle firearms with care and ensure they are unloaded before cleaning.
- Wear appropriate personal protective equipment (PPE), such as gloves and goggles, when using cleaning solvents.
- Avoid using excessive force when pushing the jag and patches through the bore to prevent damage.
- Use only compatible patches and jags with your firearm caliber to ensure proper cleaning and avoid blockages.
- Store the product in a cool, dry place away from direct sunlight and heat sources.
- Dispose of used patches and cleaning materials in accordance with local regulations.

Instructions for Installation and Usage

1. Preparation:

- Ensure the firearm is unloaded and in a safe condition for cleaning.
- Gather all necessary cleaning materials, including the BOREMAX SPEED JAG, SPEED PATCHES, and a bore cleaning solvent.

2. Installation:

- Attach the BOREMAX SPEED JAG to your cleaning rod securely.
- Ensure the jag fits snugly to prevent it from detaching during use.

3. Usage:

- Moisten the SPEED PATCH with an appropriate cleaning solvent.
- Insert the moistened SPEED PATCH onto the BOREMAX SPEED JAG.
- Carefully insert the jag with the patch into the bore of the firearm.
- Push the jag through the bore using a smooth, steady motion. Avoid excessive force.
- Remove the jag from the bore and inspect the patch for fouling.
- Repeat the process as necessary until the bore is clean.

4. PostCleaning:

- After cleaning, ensure all cleaning materials are properly disposed of.
- Store the BOREMAX SPEED JAG and SPEED PATCHES in a safe location.

Disposal Instructions

- Dispose of used patches and any cleaning solvents according to local waste management regulations.
- Do not dispose of cleaning materials in regular household waste unless specified by local guidelines.
- Recycle packaging materials where possible.

Contact Information for Further Support

For any questions or concerns regarding the BOREMAX SPEED JAG & PATCH COMBO, please refer to the manufacturer's contact information provided on the product packaging or visit their official website for further assistance.

By following these safety instructions, you can ensure a safe and effective cleaning experience with your BOREMAX SPEED JAG & PATCH COMBO. Thank you for prioritizing safety while maintaining your firearm.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk