

X-SKEL MOUNTS - WARNE MFG. COMPANY 34MM ULTRA HIGH (1.435") 0 MOA MOUNT, DARK EARTH

[Optics & Mounting](#) > [Rings, Mounts & Bases](#) > [Mount Sets](#)

Warne Scope Mounts is excited to introduce their second generation SKEL mount, the X-SKEL. This new MSR mount offers an additional 1" of forward cantilever, and 1 piece clamp design for added strength. The rugged, lightweight design of the X-SKEL maintains our famous Return to Zero capability, and utilizes 1/2" hex nuts for rock solid attachment. It features a skeletonized ring body and caps for reduced weight and steel threaded cap inserts for maximum durability. The X-SKEL places your optic at the IDEAL HEIGHT with a generous cantilever for proper eye relief, it will easily accommodate the longer eyepieces found on many of today's scopes. Lightweight, skeletonized aluminum body and caps to reduce overall weight without sacrificing reliability. #8 Torx style fasteners with steel threaded inserts to prevent stripping. Additional 1 Inch cantilever forward design to provide additional eye relief. Places your optic at the Ideal Height for MSR and similar platforms. 1/2" tactical nut attachment, 65 in/lb. of torque is recommended.



Attributes

- Name: [WARNE MFG. COMPANY 34MM ULTRA HIGH \(1.435"\) 0 MOA MOUNT, DARK EARTH](#)
- Manufacturer: [WARNE MFG. COMPANY](#)
- Product no.: 947000387
- Mfr. No.: XSkel34DE
- Finish: Dark Earth
- Scope Tube Diameter: 34mm
- Style: Competition,3-Gun
- Delivery weight: 0.227kg
- UPC: 656813104925

Item details

Made in USA

Table of Contents

- Startpage
- XSKELETON MOUNTS WARNE MFG. COMPANY 34MM ULTRA HIGH (1.435") 0 MOA MOUNT, DARK EARTH Safety Instruction Guide
- About Us

XSKELE MOUNTS WARNE MFG. COMPANY 34MM ULTRA HIGH (1.435") 0 MOA MOUNT, DARK EARTH Safety Instruction Guide

Introduction

Thank you for choosing the XSKELE Mount from Warne MFG. Company. This guide provides essential safety instructions to ensure the proper and safe use of your mount. Please read this guide carefully before installation and usage.

General Safety Guidelines

- Ensure the mount is compatible with your optic and firearm before installation.
- Keep the mount and all accessories out of reach of children and vulnerable individuals.
- Regularly inspect the mount for signs of wear or damage.
- Follow all local laws and regulations regarding firearm accessories.
- Report any unsafe products or incidents to the relevant authorities.

Specific Safety Precautions for Use

- Do not exceed the recommended torque of 65 in/lb when attaching the mount.
- Ensure that the mount is securely fastened before use to prevent accidents.
- Avoid using the mount in extreme weather conditions without prior testing.
- Do not modify the mount or use it for purposes other than intended.
- If you experience any issues with the mount, discontinue use immediately and seek assistance.

Instructions for Installation and Usage

1. Preparation

- Gather all necessary tools, including a $\frac{1}{2}$ " hex nut driver and #8 Torx style fasteners.
- Ensure you have a clean and welllit workspace.

2. Installation Steps

- Align the mount with the optic and firearm.
- Use the $\frac{1}{2}$ " tactical nut to secure the mount in place.
- Tighten the fasteners to the recommended torque of 65 in/lb.
- Doublecheck all connections to ensure they are secure.

3. Usage

- Adjust your optic to the desired height and position for optimal eye relief.
- Regularly check the mount during use to ensure it remains secure.
- If you notice any movement or instability, stop using the mount immediately.

Disposal Instructions

- Dispose of the mount and packaging materials in accordance with local regulations.
- Do not dispose of electronics or hazardous materials in regular household waste.
- Consider recycling materials where possible.

Contact Information for Further Support

For any inquiries regarding safety or product usage, please refer to the manufacturer's contact information provided with the product packaging or on the official website.

By following these guidelines, you can ensure the safe and effective use of your XSKELE Mount. Thank you for your attention to safety, and enjoy your experience with our product.

About Us

Brownells Europe

Brownells Europe - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

P.O.Box 4300
Warwick
CV34 9BR

www.brownells.eu