

QD XSKELE CANTILEVER MOUNT - WARNE MFG. COMPANY 1" ULTRA HIGH (1.435") 0 MOA QD MOUNT, BLACK

[Optics & Mounting](#) > [Rings, Mounts & Bases](#) > [Mount Sets](#)

Light and Reliable

When choosing your next mounting system, don't sacrifice reliability for weight. The Warne QD XSKELE Cantilever Mount makes that decision easy because this mount features a lightweight, skeletonized aluminum body and caps allowing it to be both light and reliable. The Warne QD XSKELE Cantilever Mount features an extended design providing over 2 inches of forward cantilever to provide you with additional eye relief and places the optic at the ideal height for your MSR and similar style platforms. 3-Gun competition style mount Steel threaded inserts for steel-on-steel contact with all threaded surfaces #8 Torx style fasteners with steel threaded inserts to prevent stripping Adding the Warne QD XSKELE Cantilever Mount to your rig will improve your performance without weighing down your gun case.



Attributes

- Name: [WARNE MFG. COMPANY 1" ULTRA HIGH \(1.435"\) 0 MOA QD MOUNT, BLACK](#)
- Manufacturer: [WARNE MFG. COMPANY](#)
- Product no.: 947000631
- Mfr. No.: QDXSKELE1TW
- Delivery weight: 0.454kg
- Shipping height: 76mm
- Shipping width: 178mm
- Shipping length: 254mm
- UPC: 656813106417

Item details

Made in USA

Table of Contents

- Startpage
- QD XSKELE Cantilever Mount Safety Instruction Guide
- About Us

QD XSKEL Cantilever Mount Safety Instruction Guide

Introduction

Thank you for choosing the Warne QD XSKEL Cantilever Mount. This guide provides essential safety instructions to ensure the safe and effective use of your mounting system. Please read this guide carefully before installation and use.

General Safety Guidelines

- Ensure safe use of the QD XSKEL Cantilever Mount by following the instructions provided in this guide.
- Be aware of potential risks associated with improper installation or usage.
- Regularly check for any recalls or safety updates related to this product.
- When purchasing online, ensure you are buying from a reputable source that meets EU safety requirements.
- If you encounter any issues or have safety concerns, report them to the appropriate authorities.

Specific Safety Precautions for Use

- Always inspect the mount for any signs of damage or wear before installation.
- Ensure that the mount is compatible with your firearm and optic before use.
- Do not exceed the manufacturer's weight limit for the mount.
- Avoid using the mount in extreme environmental conditions unless specifically designed for such use.
- Keep the mount and all installation tools out of reach of children and vulnerable individuals.
- Use the mount only for its intended purpose; do not modify or alter the mount in any way.

Instructions for Installation and Usage

1. Preparation

- Gather all necessary tools, including #8 Torx style fasteners.
- Ensure you have a clean, dry work area to perform the installation.

2. Installation Steps

- Remove any existing mounting systems from your firearm.
- Align the Warne QD XSKEL Cantilever Mount with the mounting interface on your firearm.
- Secure the mount using the provided #8 Torx style fasteners. Ensure that the steel threaded inserts are properly engaged to prevent stripping.
- Tighten all fasteners to the manufacturer's specifications, ensuring a secure fit without overtightening.

3. Optic Installation

- Once the mount is securely installed, attach your optic to the cantilever mount.
- Adjust the optic position to achieve the desired eye relief and height.
- Secure the optic according to the manufacturer's instructions.

4. Final Checks

- Inspect the installation to ensure that all components are securely fastened.
- Perform a function check to verify that the mount and optic are stable and properly aligned.

5. Usage

- Use the Warne QD XSKEL Cantilever Mount as intended. Regularly check the stability and integrity of the mount during use.
- If you notice any instability or movement, discontinue use and inspect the mount immediately.

Disposal Instructions

- Dispose of the QD XSKEL Cantilever Mount and any packaging materials in accordance with local regulations.
- Do not dispose of electronic components in regular waste. Check for local ewaste recycling programs.

Contact Information for Further Support

For any questions or concerns regarding the Warne QD XSKEL Cantilever Mount, please reach out to the manufacturer or your point of purchase for assistance. Always ensure to follow the latest safety guidelines and updates.

By adhering to these safety instructions, you can ensure a safe and enjoyable experience with your Warne QD XSKEL Cantilever Mount. Thank you for your attention to safety.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk