

Lead Sled Weight Bag, Standard - Caldwell Lead Sled Weight Bag, Large

[Shooting Accessories](#) > [Shooting Rests](#) > [Rifle Rests](#)

These stout bags are designed to be placed in the tray of your Lead Sled® 3, Solo™ or DFT™ 2 and conveniently hold a 25lb bag of lead shot, sand or other weighted media.

NO IMAGE
AVAILABLE

Attributes

- Name: [Caldwell Lead Sled Weight Bag, Large](#)
- Manufacturer: [Caldwell](#)
- Product no.: EU1001834
- Mfr. No.: 777800
- Colour: Green
- Delivery weight: 0.23kg
- Shipping height: 145mm
- Shipping width: 58mm
- Shipping length: 206mm
- UPC: 661120778004

Table of Contents

- [Startpage](#)
- [Caldwell Lead Sled Weight Bag Safety Instructions](#)
- [About Us](#)

Caldwell Lead Sled Weight Bag Safety Instructions

Introduction

Thank you for choosing the Caldwell Lead Sled Weight Bag. This product is designed to enhance the stability and performance of your Caldwell Lead Sled® 3, Solo™, or DFT™ 2. To ensure safe and effective use of this product, please read and follow these safety instructions carefully.

General Safety Guidelines

- Always ensure the weight bag is securely placed in the tray of your Lead Sled before use.
- Use only the recommended materials (25lb bag of lead shot, sand, or other weighted media) to fill the weight bag.
- Regularly inspect the weight bag for any signs of wear or damage before each use.
- Keep the weight bag out of reach of children and pets to prevent accidents.
- Do not exceed the recommended weight limit of 25lbs for the weight bag.
- In case of any malfunction or damage, discontinue use immediately and consult customer support.

Specific Safety Precautions for Use

- Ensure the weight bag is properly sealed and secured to avoid spillage of contents.
- Avoid placing the weight bag near heat sources or open flames.
- Do not attempt to modify or alter the weight bag in any way.
- Use caution when lifting or moving the weight bag, as it may be heavy when filled.
- If using outdoors, ensure the area is clear of hazards that may cause tripping or falling.

Instructions for Installation and Usage

1. Filling the Weight Bag:

- Open the weight bag and fill it with a 25lb bag of lead shot, sand, or other suitable weighted media.
- Ensure the bag is filled evenly to maintain balance.

2. Placing the Weight Bag:

- Position the filled weight bag securely in the tray of your Caldwell Lead Sled® 3, Solo™, or DFT™ 2.
- Ensure that the weight bag is stable and does not obstruct any moving parts of the Lead Sled.

3. Using the Lead Sled:

- Follow the manufacturer's instructions for operating your Lead Sled.
- Regularly check the stability of the weight bag during use to ensure safety.

4. PostUse Care:

- After use, remove the weight bag from the tray.
- Store the weight bag in a cool, dry place away from direct sunlight.

Disposal Instructions

- Dispose of the weight bag responsibly in accordance with local regulations.
- If the weight bag is damaged or no longer usable, ensure that it is disposed of in a manner that prevents environmental harm.

Contact Information for Further Support

For any inquiries regarding the Caldwell Lead Sled Weight Bag, please reach out to the appropriate customer support channels available in your region. Ensure that you have the product information ready for a more efficient response.

By following these safety instructions, you can enjoy the full benefits of your Caldwell Lead Sled Weight Bag while ensuring a safe experience. Thank you for your attention to safety and compliance with the EU General Product Safety Regulation.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk