

Lead Sled 4

[Reloading](#) > [Bullet Casting](#) > [Lead Alloy](#)

Take your shooting bench to the next level with the Caldwell Lead Sled 4. Designed for ultimate stability, this shooting rest delivers the support you need for precise shots and reduced recoil. Whether you're sighting in, testing loads, or fine-tuning your setup, the Lead Sled 4 ensures a rock-solid hold, so you can focus on performance.

Crafted with expert engineering and built from durable materials, Caldwell delivers a shooting rest that stands up to years of use. Precision, control, and reliability—it's everything you need to get the job done right.

NO IMAGE
AVAILABLE

Attributes

- Name: [Lead Sled 4](#)
- Manufacturer: [CALDWELL](#)
- Product no.: EU2014053
- Mfr. No.: 1217424
- Colour: Black
- Delivery weight: 7.44kg
- Shipping height: 651mm
- Shipping width: 274mm
- Shipping length: 305mm
- UPC: 198700000687

Table of Contents

- Startpage
- Caldwell Lead Sled 4 Safety Instruction Guide
- About Us

Caldwell Lead Sled 4 Safety Instruction Guide

Introduction

Thank you for choosing the Caldwell Lead Sled 4. This shooting rest is designed to enhance your shooting experience by providing stability and support for precise shots. To ensure safe and effective use of this product, please read and follow the safety instructions outlined in this guide.

General Safety Guidelines

- Ensure that the Lead Sled 4 is used in accordance with all local laws and regulations regarding shooting and firearms.
- Always treat firearms as if they are loaded, and follow the basic rules of firearm safety.
- Keep the shooting area clear of unauthorized persons, especially children and pets.
- Regularly inspect the Lead Sled 4 for any signs of wear or damage before each use.
- Report any unsafe conditions or incidents to the appropriate authorities immediately.

Specific Safety Precautions for Use

- Do not exceed the weight limit specified by the manufacturer for the Lead Sled 4.
- Ensure that the shooting rest is placed on a stable and level surface to prevent tipping.
- Avoid using the Lead Sled 4 in adverse weather conditions that may affect stability, such as high winds or heavy rain.
- Always secure the firearm properly in the rest to prevent accidental movement or discharge.
- Do not use the Lead Sled 4 for purposes other than its intended use as a shooting rest.

Instructions for Installation and Usage

1. Setup:

- Remove the Lead Sled 4 from its packaging and inspect for any damage.
- Place the shooting rest on a flat and stable surface at your shooting location.
- Adjust the front and rear supports to accommodate your firearm.

2. Securing the Firearm:

- Place the firearm in the designated support area of the Lead Sled 4.
- Ensure that the firearm is securely positioned and will not move during use.
- Check that all adjustments are locked in place before proceeding.

3. Shooting:

- Position yourself comfortably behind the firearm, ensuring a clear line of sight.
- Follow standard shooting practices, maintaining control of the firearm at all times.
- After shooting, always remove the firearm from the Lead Sled 4 before making any adjustments or handling.

4. PostUse:

- After use, clean the Lead Sled 4 as necessary to maintain its condition.
- Store the Lead Sled 4 in a cool, dry place, away from direct sunlight and moisture.

Disposal Instructions

- When the Lead Sled 4 has reached the end of its life or is no longer usable, dispose of it in accordance with local regulations regarding waste disposal.
- Do not dispose of the Lead Sled 4 in regular household waste if it contains materials that could be harmful to the environment.

Contact Information for Further Support

For any questions or concerns regarding the Caldwell Lead Sled 4, please refer to the manufacturer's website or contact their customer service for assistance. It is important to have a point of contact for any safety inquiries or product support.

Thank you for your attention to these safety instructions. By following these guidelines, you can ensure a safe and enjoyable shooting experience with your Caldwell Lead Sled 4.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk